

Subject: : AmigaOS4

Topic: : atheros wlan device is working

Re: atheros wlan device is working

Author: : nbache

Date: : 2020/7/4 22:33:38

URL:

@ncafferkey

Quote:

Yes, it's apparently the onboard SATA port that has a conflict with the PCIe 1x slot.

AFAIR, it's not a conflict as you normally understand it, it's simply the way the Sam460 hardware is made. You can select to use **either** the onboard SATA port **or** the PCIe 1x slot.

The choice is made by configuring it in the menu (or setting a UBoot variable directly) **and** moving a physical jumper, i.e. you need to do both things.

Best regards,

Niels