

Subject: : AmigaOS4

Topic: : Booting problem X5000

Re: Booting problem X5000

Author: : Spectre660

Date: : 2021/9/14 14:25:06

URL:

Might be worth looking at the Power supply as a possible cause.

Was having a lot of problems with my Sam460ex at startup also some with the graphics card (Rx 550)at startup until I changed back to the original mini itx power supply that came with the machine .

For some reason the regular ATX connector was not fitting securely . Also the mini itx power supply has a -5V output which the newer power supply does not .