

Subject: : AmigaOS4

Topic: : [X1000] Errors and improvement ideas for CFE

Re: [X1000] Errors and improvement ideas for CFE

Author: : Raziel

Date: : 2020/3/12 9:18:05

URL:

@corto

Nope, not seen it.

Need to read it.

Thanks Michael for posting

1) OK, so there is a bug, glad (or not really) to hear i'm not the only one.

I have 8 GB installed right now (2x4GB in banks 0 and 1, i guess).

That does work without problems here.

As soon as i add RAM to the other two bays (may it be 4x1GB, 4x2GB or 4x4GB) i get either a crash on boot or crashes while using Workbench.

So, the problem is that interweaving with banks 2 and 3 doesn't work.

I guess (really only a guess) that during CFE development none of the developers had access (or cared) to more than 4 or 8 GB and never used more than 2 RAM bars.

2) Agreed.

There is definitely something interfering which needs fixing.

otuh

- He's only one guy

- It's a hobby project within a hobby project

- He'd need to have the hardware to test (just like with KVM/Mouse/Keyboard)

edit: Judging by his answer, he's right.

the kvm problems are technically not cfe problems.

at least the ones i encounter start when i reach workbench, so yeah, point taken