

Subject: : AmigaOS4

Topic: : atheros wlan device is working

Re: atheros wlan device is working

Author: : ncafferkey

Date: : 2020/7/4 1:08:38

URL:

@Tuskagee

Yes, it's apparently the onboard SATA port that has a conflict with the PCIe 1x slot. So are you using an add-in SATA card? (Maybe that's what everyone does: as I said, I don't know much about the 460.)

Even if you don't want to use a PCI card in the 460 in the long term, I'd be interested to know if it works, as I haven't had anyone else report the results of using the new driver version on a 460. However, if that's inconvenient, don't worry about it.