
Subject: : AmigaOS4

Topic: : OS4 UPDAAAATEE !!! BANANA !!

Re: OS4 UPDAAAATEE !!! BANANA !!

Author: : Thematic

Date: : 2020/12/24 14:23:21

URL:

@kas1e

So I noticed with "v54" that any music playback was cu-t when browsing with Odyssey. Eventually I noticed simply loading this thread and pressing home/end in the context was more than enough. - The first time I thought I was running low on RAM, that's how weird this is. So the music would resume after a split second.

750FX CPU, 512 MB RAM, these:

Quote:

> pciscan

##	Vendor	Device	Vendor name	Description
01	0x10CC	0x0660	Mai Logic Incorporated	Articia S Host Bridge
02	0x10CC	0x0661	Mai Logic Incorporated	Articia S PCI Bridge
03	0x10B7	0x9200	3Com Corporation	3c905C-TX/TX-M [Tornado]
04	0x1106	0x0686	VIA Technologies, Inc.	VT82C686 [Apollo Super South]
05	0x1106	0x0571	VIA Technologies, Inc.	VT82C586A/B/VT82C686/A/B/VT823x/A/C PIPC Bus Master IDE
06	0x1106	0x3038	VIA Technologies, Inc.	VT82xxxxx UHCI USB 1.1 Controller
07	0x1106	0x3038	VIA Technologies, Inc.	VT82xxxxx UHCI USB 1.1 Controller
08	0x1106	0x3057	VIA Technologies, Inc.	VT82C686 [Apollo Super ACPI]
09	0x1106	0x3058	VIA Technologies, Inc.	VT82C686 AC97 Audio Controller
10	0x1106	0x3068	VIA Technologies, Inc.	AC'97 Modem Controller
11	0x1095	0x3112	Silicon Image, Inc.	Sil 3112 [SATALink/SATARaid] Serial ATA Controller
12	0x1319	0x0801	Fortemedia, Inc	Xwave QS3000A [FM801]
13	0x1319	0x0802	Fortemedia, Inc	Xwave QS3000A [FM801 game port]
14	0x1002	0x5961	Advanced Micro Devices, RV280	[Radeon 9200]
15	0x1002	0x5941	Advanced Micro Devices, RV280	[Radeon 9200] (Secondary)

PS/2 keyboard (right now) and some USB hub where the "actual" keyboard is attached. Mouse in rear USB port.

edit: playback on FM801, AC97 untested.