

Subject: : AmigaOS4

Topic: : New Sam460cr boards will hit the road soon!

Re: New Sam460cr boards will hit the road soon!

Author: : nbache

Date: : 2021/4/29 22:53:01

URL:

@kas1e

Quote:

Interesting through why 3114 didn't work like that? I for sake of tests tried to put 3114 back again, and set variable for + reboot, no, still no luck. But 3512 is fine always with this "sii3512ide_conf 10"

But Sil3114 has four ports, maybe you need to include all four in the flags, e.g. "setenv sii3114ide_dev 1000" or something?

Don't know if that's the problem, it just looked odd to me.

Best regards,

Niels