
Subject: : Unsatisfactory Software

Topic: : SAM460 owners - ArcEm OCM benchmarking - please help

Re: SAM460 owners - ArcEm OCM benchmarking - please help

Author: : Elwood

Date: : 2013/2/27 22:49:10

URL:

Wow, that was fast to provide an ocm enabled program!

But the result is the other way around. First the ocm version, then the standard one:

<	Clock rate:	3.0620 MHz		
>	Clock rate:	23.787 MHz		
<	High ROM access time:	325 ns		
>	High ROM access time:	450 ns		
<	Memory clock:	10.70 MHz (reported by	>	Memory clock: 65.27 MHz (reported by
OS)				